

**Prekladateľ/ Translator:** Mgr. Lucia Huličová

**Zadávateľ/ Translation made for:**

Inštitút jazykov a vzdelávania, Trieda SNP 48/A, Košice  
4 Your Education s.r.o., IČO/CRN: 46 671 072

**Dátum a miesto/ Date and Place:** 22. september 2017, Košice

**Preklad číslo 870/2017 z anglického do slovenského jazyka**  
*Official translation No. 870/2017 from English to Slovak*

**Predmet prekladu/Subject of translation:** Vyhlásenie výrobcu

**Počet strán prekladanej listiny/Počet strán prekladu:** 2/2

*Number of pages (source document/translation):*

**Počet odovzdaných vyhotovení/ Number of copies:** 1



PENTAIR  
34600 Solon Road  
Solon, OH 44139, USA  
+1.440.248.0100 main

## Manufacturer Declaration

Issued by  
ERICO International Corporation

**Equipment Description:** Isolated Lightning Conductor

**Product Name:** ISODC

**Brand Name:** ERICO

**Applicable Standards:** IEC 62305-3 Ed. 2.0 (2010) Protection against lightning – Part 3:  
Physical damage to structures and life hazard

IEC 62561-2 Ed. 1.0 (2012) Lightning protection system components  
(LPSC) – Part 2: Requirements for conductors and earth electrodes

**Test Report:** B-07-19-ERI-005e

**TR Issued by:**  
Fachhochschule Kiel  
University of Applied Sciences Kiel  
Laboratory of High Voltage Technology and EMC  
Grenzstraße 5, D-24149 Kiel

### Electrical Strength of the Isolating Lightning Conductor

The results from the Test Report listed above demonstrate that the equivalent separation distance  $s$  for the above conductor, according to standard IEC 62305-3:2010-12, subclause 6.3, corresponds to:

a maximum distance of       $s \leq 1.0 \text{ m}$       in air (material factor  $k_m = 1$ )  
a maximum distance of       $s \leq 2.0 \text{ m}$       in concrete, bricks, wood (material factor  $k_m = 0.5$ )

### Lightning Current carrying Capacity

The cable has a cross-sectional area of **50 mm<sup>2</sup>** and thus fully complies with the material, configuration and minimum cross-sectional area of air-termination conductors and down-conductors of the above Standards.



PENTAIR  
34600 Solon Road  
Solon, OH 44139, USA  
+1.440.248.0100 main

## Thermal Stress

When conducting lightning currents, the inner conductor of the ISODC conductor is expected to heat up temporarily by the following amounts:

- or      **12 K** in lightning protection systems type III/N       $I_{imp} = 100 \text{ kA (10/350 } \mu\text{s)}$
- or      **28 K** in lightning protection systems type II       $I_{imp} = 150 \text{ kA (10/350 } \mu\text{s)}$
- or      **52 K** in lightning protection systems type I       $I_{imp} = 200 \text{ kA (10/350 } \mu\text{s)}$

The ISODC conductor is unaffected by these minimal temporary temperature rises.

Authorized by:

8/18/2017

**Tom Hurney**

**Date**

**Manager, Lab & Certifications**

Subject to Change Without Notice

DOC: 00035-D

(-logo-) PENTAIR

64600 Solon Road  
Solon, OH 44139, USA  
+1.440.248.0100

## Vyhlásenie výrobcu

vydané spoločnosťou  
ERICO International Corporation

Popis zariadenia:	Izolovaný bleskozvod
Názov produktu:	ISODC
Značka:	ERICO
Aplikované normy:	IEC 62305-3 Ed. 2.0 (2010) Ochrana pred bleskom – 3. časť : Fyzické poškodenie konštrukcií a ohrozenie života IEC 62561-2 Ed. 1.0 (2012) Komponenty systému ochrany pred bleskom (LPSC) - 2. časť: Požiadavky na vodiče a uzemňovacie elektródy
Správa o skúške:	B-07-19-ERI-005e

**Správa o skúške vydaná spoločnosťou** Fachhochschule Kiel  
Univerzita aplikovaných vied Kiel  
Laboratórium vysokonapäťovej technológie a EMC  
Grenzstrasse 5, D-24149 Kiel

### Elektrická pevnosť izolovaného bleskozvodu

Výsledky vyššie uvedenej správy o skúške ukazujú, že ekvivalentný odstup s pre uvedený vodič podľa normy IEC 62305-3:2010-12, článok 6.3 zodpovedá:

maximálnej vzdialenosťi  $s \leq 1.0 \text{ m}$  vo vzduchu (materiálový faktor  $k_m = 1$ )  
maximálnej vzdialenosťi  $s \leq 2.0 \text{ m}$  v betóne, tehlách, dreve (materiálový faktor  $k_m = 0.5$ )

### Zvodová kapacita bleskového prúdu

Kábel má prierezovú plochu **50 mm<sup>2</sup>** a tým plne zodpovedá materiálu, konfiguráciu a minimálnej prierezovej oblasti zachytávajúcich a zvislých bleskozvodov vyššie uvedených nariem.

(-logo-) PENTAIR

14600 Solon Road  
Solon, OH 44139, USA  
+1.440.248.0100

## Tepelné napätie

Pri vedení bleskových prúdov sa očakáva, že vnútorný vodič bleskozvodu ISODC sa dočasne zahreje o nasledujúce hodnoty:

- 12 K** v systémoch ochrany pred bleskom typu **III/IV**       $I_{imp} = 100 \text{ kA (10/350 } \mu\text{s)}$   
alebo
- 28 K** v systémoch ochrany pred bleskom      **typu II**       $I_{imp} = 150 \text{ kA (10/350 } \mu\text{s)}$   
alebo
- 52 K** v systémoch ochrany pred bleskom      **typu I**       $I_{imp} = 200 \text{ kA (10/350 } \mu\text{s)}$

Bleskozvod ISODC nie je ovplyvnený týmito minimálnymi dočasnými zvyšovaniami teploty.

Schválil: (*-necitateľný podpis-*)  
**Tom Hurney**  
Manažér, Laboratóriá & osvedčenia

18.08.2017  
**Dátum**

Zmeny sú vyhradené bez upozornenia.

DOC: 00035-D

Preklad som vypracovala ako prekladateľka pre jazyk anglický, zapísaná v zozname znalcov tlmočníkov a prekladateľov, ktorý vedie Ministerstvo spravodlivosti Slovenskej republiky, evidenčné číslo prekladateľa 970454.


Preklad je v elektronickom denníku zapísaný pod číslom 870 /2017.

Preklad súhlasi s prekladanou listinou.

*This is to certify that I have made the above translation as the Certified Translator for English registered in the Register of Experts, Interpreters, and Translators kept with the Ministry of Justice of the Slovak Republic, translator's registration number 970454.*

*The translation has been recorded in the electronic translation journal under number 870 /2017.*

*The translation is a true and accurate translation of the source document.*



Mgr. Lucia Huličová

úradná prekladateľka / Certified Translator



AETRON S.r.o.

